

DEPARTMENT OF TRANSPORTATION	REPOR						U.S. COAST GUARD CG-2541-D11 (Rev10/97)	
INSTRUCTIONS: 1. Submit this report to the Auxiliary Coordinator as soon as possible after conducting the survey. 2. The best time to survey bridges is shortly before sunset so you can observe any hazards or discrepancies before dark, then observe the lights after dark. 3. If conducting the survey by land, respect all property rights. DO NOT TRESPASS. 4. Auxiliarists do not have law enforcement authority. Take care that your survey is not interpreted as a law enforcement action. 5. Minor discrepancies (e.g. one light out, clearance gauges hard to read) should be reported by mail. More serious problems (e.g. most or all lights out, hazards to navigation, bridge malfunction) should be reported to the nearest Coast Guard Group Office by telephone or radiotelephone. If in doubt, report it.								
NAME OF BRIDGE Needles Hwy				;	ATITUI 34 48	3' Ň	LONGTITUDE 114 36' W	
NAME OF WATERWAY Colorado River				MILES ABOVE MOUTH TYPE OF BRIDGE F				
Needles Customer Service 817 Third St Needles CA 92363							OGE OPERATOR (if different)	
Fill out the section below and annotate the diagram on the reverse. Show north arrow or direction of current.								
TYPE OF LIGHTS		Are Lights Correctly Placed?	0	re Lights f Proper olor/Arc	r	Are Lights Visible for 1 Naut. Mi?	State Condition of Lights	
Channel Center Lights	6							
Margin of Channel Lights	0							
Pier Lights	8							
Pier Axis Lights	0							
Movable Span Lights	0							
Preferred Channel Lights	0							
OTHER FEATURES	How Many?	LLNR	Ch	aracter	istic	Range	Working Properly?	
Fog Signals	0	0		N/A		N/A		
Racons	0	0	<u> </u>	N/A		N/A		
Condition of fenders: Is the bridge name shown? What name is shown? Are navigational clearances impaired by disrepair, cables, etc? Are nav. clearances impaired by accumulation of debris? Is there any equipment (e.g. barges, scaffolds) in the navigation spans that is not listed in the LNM/BNM?								
If a drawbridge, is it capable of operating? Are the operating regulations posted? Is there evidence of bridge or fender damage that might be from vessels? Discrepant Watching properly								
Name and Member Number (Date and Time of Survey						Home Telephone Number		
Date and Time of Survey	Signature of Surveyor						Aux . File Number 18	

Secondary Observer(s):	Aux. #:
·	Aux. #:
	Aux. #:
	Aux. ≇ :



NORTH ARROW



FIXED BRIDGE
(3 MARKED NAVIGATION OPENINGS)
(NO AXIS LIGHTS)

Comments: --

